Commander, Eighth Coast Guard District (oan) Hale Boggs Federal Building, Room 1230

501 Magazine Street, New Orleans, LA 70130-3396

Telephone: (504) 589-6277

(Business Hours 7:45 a.m. - 4:15 p.m. Monday - Friday)

(Nights, Weekends, Holidays) - (504) 589-6225

U.S. Department of **Homeland Security** 

**United States Coast Guard** 



## 8TH DISTRICT LOCAL NOTICE TO MARINERS MISSISSIPPI RIVER SYSTEM **WEEKLY SUPPLEMENT**

Western Rivers LIGHT LIST VOLUME V **NOTICE NUMBER 04-04** January 27, 2004

The Local Notice to Mariners consists of a Monthly Edition and Weekl y Supplements. The Monthly Edition is published the first week of each month, and Weekly Supplemental Editions are published in the intervening weeks. Weekly Supplemental Editions contain only new information; however, ongoing events/conditions published in Weekly Supplements at times are readvertised in the following Monthly Edition. Light list corrections printed in the Weekly Supplemental Editions are not repeated in Monthly Editions.

The Current Monthly Edition is Notice Number 01-04. LIGHT LIST REFERENCE: COMDTPUB P16502.4, Vol. V, 2002 Edition. CONTENTS: Rivers are listed in alphabetical order and are included only when there is information to report.

NIS WATCHSTANDER PHONE	(703) 313-5900 24-HOURS A DAY
INTERNET ADDRESSES	http://www.navcen.uscg.gov/
ZERO NOTICE INTERNET ADDRESS	http://www.navcen.uscg.gov/
WESTERN RIVERS LNM VIA INTERNET	http://www.navcen.uscg.gov/lnm/d8mrs
WESTERN RIVERS LIGHT LIST VIA INTERNET	http://www.navcen.uscg.gov/pubs/LightLists/V5COMPLETE.pdf

	BROADCAST NOTICE TO MARINERS C	OVERED IN THIS E	DITION
ORIGINATING UNITS	BEGINNING BNMS		ENDING BNMS
GROUP UPPER MISSISSIPPI RIVER	0009-04 (UM)	THROUGH	0009-04 (UM)
GROUP LOWER MISSISSIPPI RIVER	0010-04 (LM)	1	0020-04 (LM)
GROUP OHIO VALLEY	0035-04 (OV)		0043-04 (OV)
OB DWRO	0002-04 (OB)		0003-04 (OB)

		SPECIAL NOTICES
RADIOTELEPHONE SERVICE 2182.0 KHZ		ess and Calling Radiotelephone Service on the frequency 2182.0 kHz may be operating at reduced power and icture problems. Action is underway to correct these problems. The U.S. Coast Guard is operating a medium
2.020 1.1.2	frequency Digital Selective Calling Distress	ss and Safety Service on a trial operational basis only. A Global Maritime Distress and Safety System (GMDSS) waters until shoreside radio infrastructure problems can be corrected. (02-04/G-OPN)
WATERWAY ANALYSIS AND	The U. S. Coast Guard is conducting a Wa	/aterways Analysis and Management System (WAMS) study of the Ohio River, Big Sandy River and Green River.
MANAGEMENT SYSTEM STUDY		avigation system, waterborne commerce, marine casualty information, port/harbor resources, emergency response
OHIO RIVER (0.0-981.0)		ation capabilities, and future development projects. This review period will run through February 2004. Any
BIG SANDY RIVER (0.0-7.2)		to provide comments should contact the following address. You can also receive user surveys and WAMS
GREEN RIVER (0.0-149.0)	questionnaires to help in the study by E-M	Aail.
	Mail	E-Mail
	Commander	WAMS System
	U. S. Coast Guard	User Questionnaire
	Group Chio Valley	E-Mail: wgibson@gruohiovalley.uscg.mil
	600 Martin Luther King Jr. PL. Rm. 421	5 5 5
	Louisville, KY 40202-2245	
	PH: (502) 582-6439 #234	(44-03/OV 48-03 49-03 50-03 51-03 52-03)
	- , /	

	סות	COED	<b>ANCIE</b>	S AND DISCDEDANCIES CODDECTI	ח			
DISCREPANCIES AND DISCREPANCIES CORRECTED  The rivers are marked with numerous unlisted and unlighted buoys, which are periodically relocated to mark the navigational channel due to changing river conditions.								
To report Aids to Navigation discrepancies contact the nearest Coast Guard Office.								
Coast Guard Group Ohio Valley (800) 253-7465								
Coast Guard Group Upper Mississippi R								
Coast Guard Group Lower Mississippi R				(319) 524-7511 Extension 4 (901) 544-3912 Extension 122				
		MUE	DANIZ	<u> </u>	CTATUC	L NINA/DNINA		
FEDERAL AID DISCREPANCIES	LLNR	MILE	BANK	AID NAME	STATUS	LNM/BNM		
LOWER MISSISSIPPI RIVER	11495	389.8	L/B	HART LIGHT	LT EXT	04-04/0012LM		
	11540	367.7	L/B	GILES BEND CUT-OFF LIGHT	LT EXT	04-04/0011LM		
FEDERAL AID DISCREPANCIES CORRECTED	LLNR	MILE	BANK	AID NAME	STATUS	LNM/BNM		
LOWER MISSISSIPPI RIVER	9935	835.8	R/B	BADER LIGHT	WATCHING PROPERLY	04-04		
TEMPORARY CHANGES LLNR MILE BANK AID NAME STATUS		STATUS	LNM/BNM					
NONE								
TEMPORARY CHANGES CORRECTED	LLNR	MILE	BANK	AID NAME	STATUS	LNM/BNM		
NONE								
PRIVATE AID DISCREPANCIES	LLNR	MILE	BANK	AID NAME	STATUS	LNM/BNM		
UPPER MISSISSIPPI RIVER	16890	125.6	L/B	CONSOLIDATION COAL DOCK LIGHTS (3)	LT EXT	04-04/0001UM		
PRIVATE AID DISCREPANCIES CORRECTED	LLNR	MILE	BANK	AID NAME	STATUS	LNM/BNM		
CUMBERLAND RIVER	3795	193.8	L/B	NASHVILLE WATER INTAKE LIGHTS (2)	WATCHING PROPERLY	04-04		
LOWER MISSISSIPPI RIVER	9760	884.9	R/B	NEW MADRID DOCK LIGHTS (4)	WATCHING PROPERLY	04-04		
TENNESSEE RIVER	31070	462.0	L/B	COMBUSTION ENGINEERING BARGE LIGHTS (2)	WATCHING PROPERLY	04-04		
	31080	456.4	R/B	ERGON DOCK LIGHT	WATCHING PROPERLY	04-04		
	31235	431.1	R/B	TENNESSEE CONSOLIDATED COAL LIGHTS (2)	WATCHING PROPERLY	04-04		
	32025	238.8	L/B	AGRI-CHEMICALS DOCK LIGHTS (2)	WATCHING PROPERLY	04-04		

	PROPO:	SED CH	ANGES IN AIDS TO NAVIGATION	
None				

ADVANCED CHANGES IN AIDS TO NAVIGATION					TON
None					

		GENERAL INFORMATION
ARKANSAS RIVER	MILE 22.5 AIDS TO NAVIGATION	Two nun buoys previously reported missing in the vicinity of Mile 22.5, just above the Pendleton Bridge, have reportedly been reset in approximately 12 feet of water.
	UPDATE	(03-04/0008LM 04-04LM)
ILLINOIS	MILE 286.0 – MILE 285.5	Continuing until approximately March 1, 2004, the M/V LASALLE will be conducting dredging operations between approximate Miles
WATERWAY	DREDGE OPERATION	286.0 and 285.5, Brandon Road L/D Lower Approach. Work will be conducted from 7:00 a.m. to 5:00 p.m., Monday through Friday.
		The M/V LASALLE will monitor VHF-FM Channels 13, 14, or 82 and requests 30 minutes advance notice of passage. Mariners are urged to use extreme caution and transit at their slowest safe speed to minimize wake. (04-04/0009UM)
	MILE 88.8	Shoaling has been reported in the vicinity of Mile 88.8, approximately 50 feet above the Beardstown Railroad Drawbridge. A M/V
	CHANNEL CONDITION	reportedly bumped bottom at this location with a 9 foot draft with the Beardstown Gauge at 9.8 feet. Mariners are urged to exercise
		extreme caution when transiting the area. (04-04/0010UM)
	MILE 56.0	Florence Highway Drawbridge; Contractor is using a work barge in non-navigation spans on west end of the bridge for minor repair
LANDAMIA DIVED	BRIDGE REPAIR MILE 55.0	work. Although not in the navigation span, mariners should use caution when passing this site. (04-04/OB)  Commencing approximately February 3, 2004 and continuing until approximately April 15, 2004, the M/V LADY LOIS will be
KANAWHA RIVER	DREDGE OPERATION	conducting deedging operations in the vicinity of Mile 55.0, RDB. The contractor's floating plant will consist of the M/V LADY LOIS, a
	DILLOGE OF ERATION	barge mounted crane and 2 material barges. Work will be conducted between 7:00 a.m. and 5:00 p.m., Monday through Saturday.
		During non-working hours, the contractor's floating plant will be moored at the work site and lighted accordingly. The MV LADY
		LOIS will monitor VHF-FM Channel 13 for additional information. Mariners are urged to use extreme caution and transit at their
	MU F O 4	slowest safe speed to minimize wake. (04-04/COE)
LITTLE KANAWHA	MILE 0.1 SUBMERGED PIPELINE	Continuing until approximately February 23, 2004, work will be conducted to install a 24-inch submerged pipeline in the vicinity of
RIVER	CROSSING	Mile 0.1. The contractor's floating plant will consist of the M/V TOM COOK, a crane barge and a material barge. Work will be conducted from 7:00 a.m. to 5:30 p.m., Monday through Saturday. During non-working hours, the contractor's floating plant will be
	CKOSSINO	moored at the work site along the RDB and lighted accordingly. Mariners are urged to use extreme caution and transit at their
		slowest safe speed to minimize wake. (04-04/0038OV)
LOWER MISSISSIPPI	MILE 770.3	Three nun buoys previously reported missing in the vicinity of Mile 770.3, have reportedly been reset in approximately 24 feet of
RIVER	AIDS TO NAVIGATION	water with the Memphis Gauge at 19.3 feet and falling on January 22, 2004.
N. V Z. N	UPDATE	(03-04/0010LM 04-04/LM)
	MILE 734.0 - MILE 731.0 AIDS TO NAVIGATION	Several buoys previously reported missing between approximate Miles 734.0 and 731.0, have reportedly been reset in approximately 24 feet of water on January 21, 2004.
	UPDATE	approximately 24 feet of water of January 21, 2004.   (03-04/0007LM 04-04/LM)
	MILE 694.0	Two nun buoys have been reported missing in the vicinity of Mile 694.0. Mariners are urged to exercise extreme caution when
	AIDS TO NAVIGATION	transiting the area. (04-04/0019LM)
	MILE 680.0	Two nun buoys have been reported missing in the vicinity of Mile 680.0. Mariners are urged to exercise extreme caution when
	AIDS TO NAVIGATION	transiting the area. (04-04/0020LM)

		GENERAL INFORMATION/CONTINUED
UPPER MISSISSIPPI RIVER	MILE 324.9 DREDGE OPERATION	Continuing until further notice, the M/V DAVENPORT will be conducting dredging operations in the vicinity of Mile 324.9, L/D 21 Lower Auxiliary Chamber. Work will be conducted from 7:00 a.m. to 5:00 p.m., Monday through Thursday. The M/V DAVENPORT will monitor VHF-FM Channels 13, 14, or 82 and requests 30 minutes advance notice of passage. Mariners are urged to use extreme caution and transit at their slowest safe speed to minimize wake. (04-04/0008UM)
OHIO RIVER	MILE 257.0 SUNKEN BARGE	A barge has been reported sunk in the v icinity of Mile 257.0, LDB. Mariners are urged to exercise extreme caution when transiting the area. (04-04/00430V)
	MILE 605.5 CHANNEL CONDITION UPDATE	Shoaling has been reported in the vicinity of Mile 605.5, RDB, at the entrance of the Louisville and Portland Canal. The area of shoaling extends approximately 100 feet off the RDB, northern mooring cell. Depths of 8 feet over the shoal has been reported with the McAlpine L/D Gauge reading 12 feet. Mariners are urged to exercise extreme caution when transiting the area.  (03-04/0035OV 04-04/0039OV)
TENNESSEE RIVER	MILE 306.3 CHANNEL CONDITION	Shoaling has been reported in the vicinity of Mile 306.3. Two nun buoys have reportedly been set channelward of the shoal area in approximately 18 feet of water with a pool gauge of 550.5 feet, on January 24, 2004. Mariners are urged to exercise extreme caution when transiting the area. (04-04/00400V)
	MILE 22.4 L/D Information	The upstream floating guide wall at the Kentucky L/D, vicinity of Mile 22.4, has malfunctioned. All downbound tows should contact the Lockmaster prior to arrival for lockage instructions. Repairs to the floating guide wall is scheduled for February 17, 2004 through February 20, 2004. Mariners should expect intermittent delays during the repair periods. Mariners are urged to exercise extreme caution when transiting the area. (04-04/COE)

						ER SYSTEM, 2002 EDITION.	
	(* De	enotes the	column i	n which a correction has	s been made or new in	formation added.)	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	
No.	Name and Location	<u>Mile</u>	Bank	<u>Characteristic</u>	Structure/Daymark	<u>Remarks</u>	LNM
					Up Down		
None							

ENCL OCHDEC
ENCLOSURE2
None: